

ベース取付穴 Q寸法数値を一部変更

Catalog No.		テーブル					ベース			ベース取付穴				モータ取付回り																																																																																			
Type	No.	W	t2	M1	P1	P2	W1	H4	t1	h1	P3	h	Q		S		P.C.D.	D	D1	H3	N	N1	N2	N3	d	M2	ℓ																																																																						
KUA	1204	150	10	M6	<table border="1"> <tr><td>L1</td><td>P1</td></tr> <tr><td>100</td><td>50</td></tr> <tr><td>150</td><td>100</td></tr> </table>	L1	P1	100	50	150	100	110	145	42	10	13	75	9.5	<table border="1"> <tr><td>L</td><td colspan="2">Q</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>6</td><td>6</td></tr> <tr><td>400</td><td>6</td><td>8</td></tr> <tr><td>460</td><td>8</td><td>8</td></tr> <tr><td>520</td><td>8</td><td>10</td></tr> <tr><td>580</td><td>10</td><td>10</td></tr> <tr><td>640</td><td>10</td><td>12</td></tr> <tr><td>700</td><td>12</td><td>12</td></tr> <tr><td>760</td><td>12</td><td>14</td></tr> <tr><td>820</td><td>14</td><td>14</td></tr> </table>	L	Q			W=150	W=200	340	6	6	400	6	8	460	8	8	520	8	10	580	10	10	640	10	12	700	12	12	760	12	14	820	14	14	<table border="1"> <tr><td>L</td><td colspan="2">S</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>50</td><td>50</td></tr> <tr><td>400</td><td>80</td><td>20</td></tr> <tr><td>460</td><td>50</td><td>50</td></tr> <tr><td>520</td><td>80</td><td>20</td></tr> <tr><td>580</td><td>50</td><td>50</td></tr> <tr><td>640</td><td>80</td><td>20</td></tr> <tr><td>700</td><td>50</td><td>50</td></tr> <tr><td>760</td><td>80</td><td>20</td></tr> <tr><td>820</td><td>50</td><td>50</td></tr> </table>	L	S			W=150	W=200	340	50	50	400	80	20	460	50	50	520	80	20	580	50	50	640	80	20	700	50	50	760	80	20	820	50	50	46	30	34	49	37	5	32	15	8	M4	8
	L1					P1																																																																																											
	100					50																																																																																											
	150					100																																																																																											
	L	Q																																																																																															
		W=150	W=200																																																																																														
	340	6	6																																																																																														
	400	6	8																																																																																														
	460	8	8																																																																																														
	520	8	10																																																																																														
	580	10	10																																																																																														
	640	10	12																																																																																														
700	12	12																																																																																															
760	12	14																																																																																															
820	14	14																																																																																															
L	S																																																																																																
	W=150	W=200																																																																																															
340	50	50																																																																																															
400	80	20																																																																																															
460	50	50																																																																																															
520	80	20																																																																																															
580	50	50																																																																																															
640	80	20																																																																																															
700	50	50																																																																																															
760	80	20																																																																																															
820	50	50																																																																																															
1210	200	12	<table border="1"> <tr><td>L1</td><td>P1</td></tr> <tr><td>150</td><td>80</td></tr> <tr><td>200</td><td>130</td></tr> </table>	L1	P1	150	80	200	130	160	195	42	10	13	9.5	<table border="1"> <tr><td>L</td><td colspan="2">Q</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>6</td><td>6</td></tr> <tr><td>400</td><td>6</td><td>8</td></tr> <tr><td>460</td><td>8</td><td>8</td></tr> <tr><td>520</td><td>8</td><td>10</td></tr> <tr><td>580</td><td>10</td><td>10</td></tr> <tr><td>640</td><td>10</td><td>12</td></tr> <tr><td>700</td><td>12</td><td>12</td></tr> <tr><td>760</td><td>12</td><td>14</td></tr> <tr><td>820</td><td>14</td><td>14</td></tr> </table>	L	Q			W=150	W=200	340	6	6	400	6	8	460	8	8	520	8	10	580	10	10	640	10	12	700	12	12	760	12	14	820	14	14	<table border="1"> <tr><td>L</td><td colspan="2">S</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>50</td><td>50</td></tr> <tr><td>400</td><td>80</td><td>20</td></tr> <tr><td>460</td><td>50</td><td>50</td></tr> <tr><td>520</td><td>80</td><td>20</td></tr> <tr><td>580</td><td>50</td><td>50</td></tr> <tr><td>640</td><td>80</td><td>20</td></tr> <tr><td>700</td><td>50</td><td>50</td></tr> <tr><td>760</td><td>80</td><td>20</td></tr> <tr><td>820</td><td>50</td><td>50</td></tr> </table>	L	S			W=150	W=200	340	50	50	400	80	20	460	50	50	520	80	20	580	50	50	640	80	20	700	50	50	760	80	20	820	50	50	70	50	45	62	45	40	10	M5	10					
L1				P1																																																																																													
150				80																																																																																													
200	130																																																																																																
L	Q																																																																																																
	W=150	W=200																																																																																															
340	6	6																																																																																															
400	6	8																																																																																															
460	8	8																																																																																															
520	8	10																																																																																															
580	10	10																																																																																															
640	10	12																																																																																															
700	12	12																																																																																															
760	12	14																																																																																															
820	14	14																																																																																															
L	S																																																																																																
	W=150	W=200																																																																																															
340	50	50																																																																																															
400	80	20																																																																																															
460	50	50																																																																																															
520	80	20																																																																																															
580	50	50																																																																																															
640	80	20																																																																																															
700	50	50																																																																																															
760	80	20																																																																																															
820	50	50																																																																																															
1505	12	<table border="1"> <tr><td>L1</td><td>P1</td></tr> <tr><td>150</td><td>100</td></tr> <tr><td>200</td><td>150</td></tr> </table>	L1	P1	150	100	200	150	150	155	49	12	20	11.5	<table border="1"> <tr><td>L</td><td colspan="2">Q</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>6</td><td>6</td></tr> <tr><td>400</td><td>6</td><td>8</td></tr> <tr><td>460</td><td>8</td><td>8</td></tr> <tr><td>520</td><td>8</td><td>10</td></tr> <tr><td>580</td><td>10</td><td>10</td></tr> <tr><td>640</td><td>10</td><td>12</td></tr> <tr><td>700</td><td>12</td><td>12</td></tr> <tr><td>760</td><td>12</td><td>14</td></tr> <tr><td>820</td><td>14</td><td>14</td></tr> </table>	L	Q			W=150	W=200	340	6	6	400	6	8	460	8	8	520	8	10	580	10	10	640	10	12	700	12	12	760	12	14	820	14	14	<table border="1"> <tr><td>L</td><td colspan="2">S</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>50</td><td>50</td></tr> <tr><td>400</td><td>80</td><td>20</td></tr> <tr><td>460</td><td>50</td><td>50</td></tr> <tr><td>520</td><td>80</td><td>20</td></tr> <tr><td>580</td><td>50</td><td>50</td></tr> <tr><td>640</td><td>80</td><td>20</td></tr> <tr><td>700</td><td>50</td><td>50</td></tr> <tr><td>760</td><td>80</td><td>20</td></tr> <tr><td>820</td><td>50</td><td>50</td></tr> </table>	L	S			W=150	W=200	340	50	50	400	80	20	460	50	50	520	80	20	580	50	50	640	80	20	700	50	50	760	80	20	820	50	50	46	30	34	49	37	32	8	M4	8						
L1			P1																																																																																														
150	100																																																																																																
200	150																																																																																																
L	Q																																																																																																
	W=150	W=200																																																																																															
340	6	6																																																																																															
400	6	8																																																																																															
460	8	8																																																																																															
520	8	10																																																																																															
580	10	10																																																																																															
640	10	12																																																																																															
700	12	12																																																																																															
760	12	14																																																																																															
820	14	14																																																																																															
L	S																																																																																																
	W=150	W=200																																																																																															
340	50	50																																																																																															
400	80	20																																																																																															
460	50	50																																																																																															
520	80	20																																																																																															
580	50	50																																																																																															
640	80	20																																																																																															
700	50	50																																																																																															
760	80	20																																																																																															
820	50	50																																																																																															
1510	10	<table border="1"> <tr><td>L1</td><td>P1</td></tr> <tr><td>150</td><td>80</td></tr> <tr><td>200</td><td>130</td></tr> </table>	L1	P1	150	80	200	130	160	195	49	12	20	11.5	<table border="1"> <tr><td>L</td><td colspan="2">Q</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>6</td><td>6</td></tr> <tr><td>400</td><td>6</td><td>8</td></tr> <tr><td>460</td><td>8</td><td>8</td></tr> <tr><td>520</td><td>8</td><td>10</td></tr> <tr><td>580</td><td>10</td><td>10</td></tr> <tr><td>640</td><td>10</td><td>12</td></tr> <tr><td>700</td><td>12</td><td>12</td></tr> <tr><td>760</td><td>12</td><td>14</td></tr> <tr><td>820</td><td>14</td><td>14</td></tr> </table>	L	Q			W=150	W=200	340	6	6	400	6	8	460	8	8	520	8	10	580	10	10	640	10	12	700	12	12	760	12	14	820	14	14	<table border="1"> <tr><td>L</td><td colspan="2">S</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>50</td><td>50</td></tr> <tr><td>400</td><td>80</td><td>20</td></tr> <tr><td>460</td><td>50</td><td>50</td></tr> <tr><td>520</td><td>80</td><td>20</td></tr> <tr><td>580</td><td>50</td><td>50</td></tr> <tr><td>640</td><td>80</td><td>20</td></tr> <tr><td>700</td><td>50</td><td>50</td></tr> <tr><td>760</td><td>80</td><td>20</td></tr> <tr><td>820</td><td>50</td><td>50</td></tr> </table>	L	S			W=150	W=200	340	50	50	400	80	20	460	50	50	520	80	20	580	50	50	640	80	20	700	50	50	760	80	20	820	50	50	70	50	45	62	45	40	10	M5	10						
L1			P1																																																																																														
150	80																																																																																																
200	130																																																																																																
L	Q																																																																																																
	W=150	W=200																																																																																															
340	6	6																																																																																															
400	6	8																																																																																															
460	8	8																																																																																															
520	8	10																																																																																															
580	10	10																																																																																															
640	10	12																																																																																															
700	12	12																																																																																															
760	12	14																																																																																															
820	14	14																																																																																															
L	S																																																																																																
	W=150	W=200																																																																																															
340	50	50																																																																																															
400	80	20																																																																																															
460	50	50																																																																																															
520	80	20																																																																																															
580	50	50																																																																																															
640	80	20																																																																																															
700	50	50																																																																																															
760	80	20																																																																																															
820	50	50																																																																																															
1520	12	<table border="1"> <tr><td>L1</td><td>P1</td></tr> <tr><td>150</td><td>100</td></tr> <tr><td>200</td><td>150</td></tr> </table>	L1	P1	150	100	200	150	150	155	55	12	20	11.5	<table border="1"> <tr><td>L</td><td colspan="2">Q</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>6</td><td>6</td></tr> <tr><td>400</td><td>6</td><td>8</td></tr> <tr><td>460</td><td>8</td><td>8</td></tr> <tr><td>520</td><td>8</td><td>10</td></tr> <tr><td>580</td><td>10</td><td>10</td></tr> <tr><td>640</td><td>10</td><td>12</td></tr> <tr><td>700</td><td>12</td><td>12</td></tr> <tr><td>760</td><td>12</td><td>14</td></tr> <tr><td>820</td><td>14</td><td>14</td></tr> </table>	L	Q			W=150	W=200	340	6	6	400	6	8	460	8	8	520	8	10	580	10	10	640	10	12	700	12	12	760	12	14	820	14	14	<table border="1"> <tr><td>L</td><td colspan="2">S</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>50</td><td>50</td></tr> <tr><td>400</td><td>80</td><td>20</td></tr> <tr><td>460</td><td>50</td><td>50</td></tr> <tr><td>520</td><td>80</td><td>20</td></tr> <tr><td>580</td><td>50</td><td>50</td></tr> <tr><td>640</td><td>80</td><td>20</td></tr> <tr><td>700</td><td>50</td><td>50</td></tr> <tr><td>760</td><td>80</td><td>20</td></tr> <tr><td>820</td><td>50</td><td>50</td></tr> </table>	L	S			W=150	W=200	340	50	50	400	80	20	460	50	50	520	80	20	580	50	50	640	80	20	700	50	50	760	80	20	820	50	50	46	30	34	49	37	32	8	M4	8						
L1			P1																																																																																														
150	100																																																																																																
200	150																																																																																																
L	Q																																																																																																
	W=150	W=200																																																																																															
340	6	6																																																																																															
400	6	8																																																																																															
460	8	8																																																																																															
520	8	10																																																																																															
580	10	10																																																																																															
640	10	12																																																																																															
700	12	12																																																																																															
760	12	14																																																																																															
820	14	14																																																																																															
L	S																																																																																																
	W=150	W=200																																																																																															
340	50	50																																																																																															
400	80	20																																																																																															
460	50	50																																																																																															
520	80	20																																																																																															
580	50	50																																																																																															
640	80	20																																																																																															
700	50	50																																																																																															
760	80	20																																																																																															
820	50	50																																																																																															
1204L	10	<table border="1"> <tr><td>L1</td><td>P1</td></tr> <tr><td>150</td><td>80</td></tr> <tr><td>200</td><td>130</td></tr> </table>	L1	P1	150	80	200	130	160	195	55	12	20	11.5	<table border="1"> <tr><td>L</td><td colspan="2">Q</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>6</td><td>6</td></tr> <tr><td>400</td><td>6</td><td>8</td></tr> <tr><td>460</td><td>8</td><td>8</td></tr> <tr><td>520</td><td>8</td><td>10</td></tr> <tr><td>580</td><td>10</td><td>10</td></tr> <tr><td>640</td><td>10</td><td>12</td></tr> <tr><td>700</td><td>12</td><td>12</td></tr> <tr><td>760</td><td>12</td><td>14</td></tr> <tr><td>820</td><td>14</td><td>14</td></tr> </table>	L	Q			W=150	W=200	340	6	6	400	6	8	460	8	8	520	8	10	580	10	10	640	10	12	700	12	12	760	12	14	820	14	14	<table border="1"> <tr><td>L</td><td colspan="2">S</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>50</td><td>50</td></tr> <tr><td>400</td><td>80</td><td>20</td></tr> <tr><td>460</td><td>50</td><td>50</td></tr> <tr><td>520</td><td>80</td><td>20</td></tr> <tr><td>580</td><td>50</td><td>50</td></tr> <tr><td>640</td><td>80</td><td>20</td></tr> <tr><td>700</td><td>50</td><td>50</td></tr> <tr><td>760</td><td>80</td><td>20</td></tr> <tr><td>820</td><td>50</td><td>50</td></tr> </table>	L	S			W=150	W=200	340	50	50	400	80	20	460	50	50	520	80	20	580	50	50	640	80	20	700	50	50	760	80	20	820	50	50	70	50	45	62	45	40	10	M5	10						
L1			P1																																																																																														
150	80																																																																																																
200	130																																																																																																
L	Q																																																																																																
	W=150	W=200																																																																																															
340	6	6																																																																																															
400	6	8																																																																																															
460	8	8																																																																																															
520	8	10																																																																																															
580	10	10																																																																																															
640	10	12																																																																																															
700	12	12																																																																																															
760	12	14																																																																																															
820	14	14																																																																																															
L	S																																																																																																
	W=150	W=200																																																																																															
340	50	50																																																																																															
400	80	20																																																																																															
460	50	50																																																																																															
520	80	20																																																																																															
580	50	50																																																																																															
640	80	20																																																																																															
700	50	50																																																																																															
760	80	20																																																																																															
820	50	50																																																																																															
1210L	12	<table border="1"> <tr><td>L1</td><td>P1</td></tr> <tr><td>150</td><td>100</td></tr> <tr><td>200</td><td>150</td></tr> </table>	L1	P1	150	100	200	150	150	155	61	12	29	11.5	<table border="1"> <tr><td>L</td><td colspan="2">Q</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>6</td><td>6</td></tr> <tr><td>400</td><td>6</td><td>8</td></tr> <tr><td>460</td><td>8</td><td>8</td></tr> <tr><td>520</td><td>8</td><td>10</td></tr> <tr><td>580</td><td>10</td><td>10</td></tr> <tr><td>640</td><td>10</td><td>12</td></tr> <tr><td>700</td><td>12</td><td>12</td></tr> <tr><td>760</td><td>12</td><td>14</td></tr> <tr><td>820</td><td>14</td><td>14</td></tr> </table>	L	Q			W=150	W=200	340	6	6	400	6	8	460	8	8	520	8	10	580	10	10	640	10	12	700	12	12	760	12	14	820	14	14	<table border="1"> <tr><td>L</td><td colspan="2">S</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>50</td><td>50</td></tr> <tr><td>400</td><td>80</td><td>20</td></tr> <tr><td>460</td><td>50</td><td>50</td></tr> <tr><td>520</td><td>80</td><td>20</td></tr> <tr><td>580</td><td>50</td><td>50</td></tr> <tr><td>640</td><td>80</td><td>20</td></tr> <tr><td>700</td><td>50</td><td>50</td></tr> <tr><td>760</td><td>80</td><td>20</td></tr> <tr><td>820</td><td>50</td><td>50</td></tr> </table>	L	S			W=150	W=200	340	50	50	400	80	20	460	50	50	520	80	20	580	50	50	640	80	20	700	50	50	760	80	20	820	50	50	70	50	45	64	57.5	39.5	18	12	M5	10					
L1			P1																																																																																														
150	100																																																																																																
200	150																																																																																																
L	Q																																																																																																
	W=150	W=200																																																																																															
340	6	6																																																																																															
400	6	8																																																																																															
460	8	8																																																																																															
520	8	10																																																																																															
580	10	10																																																																																															
640	10	12																																																																																															
700	12	12																																																																																															
760	12	14																																																																																															
820	14	14																																																																																															
L	S																																																																																																
	W=150	W=200																																																																																															
340	50	50																																																																																															
400	80	20																																																																																															
460	50	50																																																																																															
520	80	20																																																																																															
580	50	50																																																																																															
640	80	20																																																																																															
700	50	50																																																																																															
760	80	20																																																																																															
820	50	50																																																																																															
1505L	10	<table border="1"> <tr><td>L1</td><td>P1</td></tr> <tr><td>150</td><td>80</td></tr> <tr><td>200</td><td>130</td></tr> </table>	L1	P1	150	80	200	130	160	195	61	12	29	11.5	<table border="1"> <tr><td>L</td><td colspan="2">Q</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>6</td><td>6</td></tr> <tr><td>400</td><td>6</td><td>8</td></tr> <tr><td>460</td><td>8</td><td>8</td></tr> <tr><td>520</td><td>8</td><td>10</td></tr> <tr><td>580</td><td>10</td><td>10</td></tr> <tr><td>640</td><td>10</td><td>12</td></tr> <tr><td>700</td><td>12</td><td>12</td></tr> <tr><td>760</td><td>12</td><td>14</td></tr> <tr><td>820</td><td>14</td><td>14</td></tr> </table>	L	Q			W=150	W=200	340	6	6	400	6	8	460	8	8	520	8	10	580	10	10	640	10	12	700	12	12	760	12	14	820	14	14	<table border="1"> <tr><td>L</td><td colspan="2">S</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>50</td><td>50</td></tr> <tr><td>400</td><td>80</td><td>20</td></tr> <tr><td>460</td><td>50</td><td>50</td></tr> <tr><td>520</td><td>80</td><td>20</td></tr> <tr><td>580</td><td>50</td><td>50</td></tr> <tr><td>640</td><td>80</td><td>20</td></tr> <tr><td>700</td><td>50</td><td>50</td></tr> <tr><td>760</td><td>80</td><td>20</td></tr> <tr><td>820</td><td>50</td><td>50</td></tr> </table>	L	S			W=150	W=200	340	50	50	400	80	20	460	50	50	520	80	20	580	50	50	640	80	20	700	50	50	760	80	20	820	50	50	70	50	45	64	57.5	39.5	18	12	M5	10					
L1			P1																																																																																														
150	80																																																																																																
200	130																																																																																																
L	Q																																																																																																
	W=150	W=200																																																																																															
340	6	6																																																																																															
400	6	8																																																																																															
460	8	8																																																																																															
520	8	10																																																																																															
580	10	10																																																																																															
640	10	12																																																																																															
700	12	12																																																																																															
760	12	14																																																																																															
820	14	14																																																																																															
L	S																																																																																																
	W=150	W=200																																																																																															
340	50	50																																																																																															
400	80	20																																																																																															
460	50	50																																																																																															
520	80	20																																																																																															
580	50	50																																																																																															
640	80	20																																																																																															
700	50	50																																																																																															
760	80	20																																																																																															
820	50	50																																																																																															
1510L	12	<table border="1"> <tr><td>L1</td><td>P1</td></tr> <tr><td>150</td><td>100</td></tr> <tr><td>200</td><td>150</td></tr> </table>	L1	P1	150	100	200	150	150	155	61	12	29	11.5	<table border="1"> <tr><td>L</td><td colspan="2">Q</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>6</td><td>6</td></tr> <tr><td>400</td><td>6</td><td>8</td></tr> <tr><td>460</td><td>8</td><td>8</td></tr> <tr><td>520</td><td>8</td><td>10</td></tr> <tr><td>580</td><td>10</td><td>10</td></tr> <tr><td>640</td><td>10</td><td>12</td></tr> <tr><td>700</td><td>12</td><td>12</td></tr> <tr><td>760</td><td>12</td><td>14</td></tr> <tr><td>820</td><td>14</td><td>14</td></tr> </table>	L	Q			W=150	W=200	340	6	6	400	6	8	460	8	8	520	8	10	580	10	10	640	10	12	700	12	12	760	12	14	820	14	14	<table border="1"> <tr><td>L</td><td colspan="2">S</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>50</td><td>50</td></tr> <tr><td>400</td><td>80</td><td>20</td></tr> <tr><td>460</td><td>50</td><td>50</td></tr> <tr><td>520</td><td>80</td><td>20</td></tr> <tr><td>580</td><td>50</td><td>50</td></tr> <tr><td>640</td><td>80</td><td>20</td></tr> <tr><td>700</td><td>50</td><td>50</td></tr> <tr><td>760</td><td>80</td><td>20</td></tr> <tr><td>820</td><td>50</td><td>50</td></tr> </table>	L	S			W=150	W=200	340	50	50	400	80	20	460	50	50	520	80	20	580	50	50	640	80	20	700	50	50	760	80	20	820	50	50	70	50	45	64	57.5	39.5	18	12	M5	10					
L1			P1																																																																																														
150	100																																																																																																
200	150																																																																																																
L	Q																																																																																																
	W=150	W=200																																																																																															
340	6	6																																																																																															
400	6	8																																																																																															
460	8	8																																																																																															
520	8	10																																																																																															
580	10	10																																																																																															
640	10	12																																																																																															
700	12	12																																																																																															
760	12	14																																																																																															
820	14	14																																																																																															
L	S																																																																																																
	W=150	W=200																																																																																															
340	50	50																																																																																															
400	80	20																																																																																															
460	50	50																																																																																															
520	80	20																																																																																															
580	50	50																																																																																															
640	80	20																																																																																															
700	50	50																																																																																															
760	80	20																																																																																															
820	50	50																																																																																															
1520L	10	<table border="1"> <tr><td>L1</td><td>P1</td></tr> <tr><td>150</td><td>80</td></tr> <tr><td>200</td><td>130</td></tr> </table>	L1	P1	150	80	200	130	160	195	61	12	29	11.5	<table border="1"> <tr><td>L</td><td colspan="2">Q</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>6</td><td>6</td></tr> <tr><td>400</td><td>6</td><td>8</td></tr> <tr><td>460</td><td>8</td><td>8</td></tr> <tr><td>520</td><td>8</td><td>10</td></tr> <tr><td>580</td><td>10</td><td>10</td></tr> <tr><td>640</td><td>10</td><td>12</td></tr> <tr><td>700</td><td>12</td><td>12</td></tr> <tr><td>760</td><td>12</td><td>14</td></tr> <tr><td>820</td><td>14</td><td>14</td></tr> </table>	L	Q			W=150	W=200	340	6	6	400	6	8	460	8	8	520	8	10	580	10	10	640	10	12	700	12	12	760	12	14	820	14	14	<table border="1"> <tr><td>L</td><td colspan="2">S</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>50</td><td>50</td></tr> <tr><td>400</td><td>80</td><td>20</td></tr> <tr><td>460</td><td>50</td><td>50</td></tr> <tr><td>520</td><td>80</td><td>20</td></tr> <tr><td>580</td><td>50</td><td>50</td></tr> <tr><td>640</td><td>80</td><td>20</td></tr> <tr><td>700</td><td>50</td><td>50</td></tr> <tr><td>760</td><td>80</td><td>20</td></tr> <tr><td>820</td><td>50</td><td>50</td></tr> </table>	L	S			W=150	W=200	340	50	50	400	80	20	460	50	50	520	80	20	580	50	50	640	80	20	700	50	50	760	80	20	820	50	50	70	50	45	64	57.5	39.5	18	12	M5	10					
L1			P1																																																																																														
150	80																																																																																																
200	130																																																																																																
L	Q																																																																																																
	W=150	W=200																																																																																															
340	6	6																																																																																															
400	6	8																																																																																															
460	8	8																																																																																															
520	8	10																																																																																															
580	10	10																																																																																															
640	10	12																																																																																															
700	12	12																																																																																															
760	12	14																																																																																															
820	14	14																																																																																															
L	S																																																																																																
	W=150	W=200																																																																																															
340	50	50																																																																																															
400	80	20																																																																																															
460	50	50																																																																																															
520	80	20																																																																																															
580	50	50																																																																																															
640	80	20																																																																																															
700	50	50																																																																																															
760	80	20																																																																																															
820	50	50																																																																																															
2005L	12	<table border="1"> <tr><td>L1</td><td>P1</td></tr> <tr><td>150</td><td>100</td></tr> <tr><td>200</td><td>150</td></tr> </table>	L1	P1	150	100	200	150	150	155	61	12	29	11.5	<table border="1"> <tr><td>L</td><td colspan="2">Q</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>6</td><td>6</td></tr> <tr><td>400</td><td>6</td><td>8</td></tr> <tr><td>460</td><td>8</td><td>8</td></tr> <tr><td>520</td><td>8</td><td>10</td></tr> <tr><td>580</td><td>10</td><td>10</td></tr> <tr><td>640</td><td>10</td><td>12</td></tr> <tr><td>700</td><td>12</td><td>12</td></tr> <tr><td>760</td><td>12</td><td>14</td></tr> <tr><td>820</td><td>14</td><td>14</td></tr> </table>	L	Q			W=150	W=200	340	6	6	400	6	8	460	8	8	520	8	10	580	10	10	640	10	12	700	12	12	760	12	14	820	14	14	<table border="1"> <tr><td>L</td><td colspan="2">S</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>50</td><td>50</td></tr> <tr><td>400</td><td>80</td><td>20</td></tr> <tr><td>460</td><td>50</td><td>50</td></tr> <tr><td>520</td><td>80</td><td>20</td></tr> <tr><td>580</td><td>50</td><td>50</td></tr> <tr><td>640</td><td>80</td><td>20</td></tr> <tr><td>700</td><td>50</td><td>50</td></tr> <tr><td>760</td><td>80</td><td>20</td></tr> <tr><td>820</td><td>50</td><td>50</td></tr> </table>	L	S			W=150	W=200	340	50	50	400	80	20	460	50	50	520	80	20	580	50	50	640	80	20	700	50	50	760	80	20	820	50	50	70	50	45	64	57.5	39.5	18	12	M5	10					
L1			P1																																																																																														
150	100																																																																																																
200	150																																																																																																
L	Q																																																																																																
	W=150	W=200																																																																																															
340	6	6																																																																																															
400	6	8																																																																																															
460	8	8																																																																																															
520	8	10																																																																																															
580	10	10																																																																																															
640	10	12																																																																																															
700	12	12																																																																																															
760	12	14																																																																																															
820	14	14																																																																																															
L	S																																																																																																
	W=150	W=200																																																																																															
340	50	50																																																																																															
400	80	20																																																																																															
460	50	50																																																																																															
520	80	20																																																																																															
580	50	50																																																																																															
640	80	20																																																																																															
700	50	50																																																																																															
760	80	20																																																																																															
820	50	50																																																																																															
2010L	10	<table border="1"> <tr><td>L1</td><td>P1</td></tr> <tr><td>150</td><td>80</td></tr> <tr><td>200</td><td>130</td></tr> </table>	L1	P1	150	80	200	130	160	195	61	12	29	11.5	<table border="1"> <tr><td>L</td><td colspan="2">Q</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>6</td><td>6</td></tr> <tr><td>400</td><td>6</td><td>8</td></tr> <tr><td>460</td><td>8</td><td>8</td></tr> <tr><td>520</td><td>8</td><td>10</td></tr> <tr><td>580</td><td>10</td><td>10</td></tr> <tr><td>640</td><td>10</td><td>12</td></tr> <tr><td>700</td><td>12</td><td>12</td></tr> <tr><td>760</td><td>12</td><td>14</td></tr> <tr><td>820</td><td>14</td><td>14</td></tr> </table>	L	Q			W=150	W=200	340	6	6	400	6	8	460	8	8	520	8	10	580	10	10	640	10	12	700	12	12	760	12	14	820	14	14	<table border="1"> <tr><td>L</td><td colspan="2">S</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>50</td><td>50</td></tr> <tr><td>400</td><td>80</td><td>20</td></tr> <tr><td>460</td><td>50</td><td>50</td></tr> <tr><td>520</td><td>80</td><td>20</td></tr> <tr><td>580</td><td>50</td><td>50</td></tr> <tr><td>640</td><td>80</td><td>20</td></tr> <tr><td>700</td><td>50</td><td>50</td></tr> <tr><td>760</td><td>80</td><td>20</td></tr> <tr><td>820</td><td>50</td><td>50</td></tr> </table>	L	S			W=150	W=200	340	50	50	400	80	20	460	50	50	520	80	20	580	50	50	640	80	20	700	50	50	760	80	20	820	50	50	70	50	45	64	57.5	39.5	18	12	M5	10					
L1			P1																																																																																														
150	80																																																																																																
200	130																																																																																																
L	Q																																																																																																
	W=150	W=200																																																																																															
340	6	6																																																																																															
400	6	8																																																																																															
460	8	8																																																																																															
520	8	10																																																																																															
580	10	10																																																																																															
640	10	12																																																																																															
700	12	12																																																																																															
760	12	14																																																																																															
820	14	14																																																																																															
L	S																																																																																																
	W=150	W=200																																																																																															
340	50	50																																																																																															
400	80	20																																																																																															
460	50	50																																																																																															
520	80	20																																																																																															
580	50	50																																																																																															
640	80	20																																																																																															
700	50	50																																																																																															
760	80	20																																																																																															
820	50	50																																																																																															
2020L	12	<table border="1"> <tr><td>L1</td><td>P1</td></tr> <tr><td>150</td><td>100</td></tr> <tr><td>200</td><td>150</td></tr> </table>	L1	P1	150	100	200	150	150	155	61	12	29	11.5	<table border="1"> <tr><td>L</td><td colspan="2">Q</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>6</td><td>6</td></tr> <tr><td>400</td><td>6</td><td>8</td></tr> <tr><td>460</td><td>8</td><td>8</td></tr> <tr><td>520</td><td>8</td><td>10</td></tr> <tr><td>580</td><td>10</td><td>10</td></tr> <tr><td>640</td><td>10</td><td>12</td></tr> <tr><td>700</td><td>12</td><td>12</td></tr> <tr><td>760</td><td>12</td><td>14</td></tr> <tr><td>820</td><td>14</td><td>14</td></tr> </table>	L	Q			W=150	W=200	340	6	6	400	6	8	460	8	8	520	8	10	580	10	10	640	10	12	700	12	12	760	12	14	820	14	14	<table border="1"> <tr><td>L</td><td colspan="2">S</td></tr> <tr><td></td><td>W=150</td><td>W=200</td></tr> <tr><td>340</td><td>50</td><td>50</td></tr> <tr><td>400</td><td>80</td><td>20</td></tr> <tr><td>460</td><td>50</td><td>50</td></tr> <tr><td>520</td><td>80</td><td>20</td></tr> <tr><td>580</td><td>50</td><td>50</td></tr> <tr><td>640</td><td>80</td><td>20</td></tr> <tr><td>700</td><td>50</td><td>50</td></tr> <tr><td>760</td><td>80</td><td>20</td></tr> <tr><td>820</td><td>50</td><td>50</td></tr> </table>	L	S			W=150	W=200	340	50	50	400	80	20	460	50	50	520	80	20	580	50	50	640	80	20	700	50	50	760	80	20	820	50	50	70	50	45	64	57.5	39.5	18	12	M5	10					
L1			P1																																																																																														
150	100																																																																																																
200	150																																																																																																
L	Q																																																																																																
	W=150	W=200																																																																																															
340	6	6																																																																																															
400	6	8																																																																																															
460	8	8																																																																																															
520	8	10																																																																																															
580	10	10																																																																																															
640	10	12																																																																																															
700	12	12																																																																																															
760	12	14																																																																																															
820	14	14																																																																																															
L	S																																																																																																
	W=150	W=200																																																																																															
340	50	50																																																																																															
400	80	20																																																																																															
460	50	50																																																																																															
520	80	20																																																																																															
580	50	50																																																																																															
640	80	20																																																																																															
700	50	50																																																																																															
760	80	20																																																																																															
820	50	50																																																																																															

<訂正用>

L	Q	
	W=150	W=200
340	6	6
400	6	8
460	8	8
520	8	1